
105/16-15 MED

#2 Ideal blade and head is recommended

High heat, fast track conditions

Narrow circumferential grooves

do not groove through the leading edge. This will help maintain a sharp leading edge.



Narrow circumferential sipes. Approximately half depth.

Notes:

- -Circumferential siping and grooving helps dissipate heat.
 Also helps with sidebite.
- Cross grooving helps with forward bite and removing loose dirt.